

Errata for the January 2007 version of the USGBC Colorado Chapter LEED Professional Accreditation Study Guide

*Items corrected in **March, 2007** and thus not relevant for copies distributed thereafter.*

Item 1

Page 52, Practice Exam question #1 should have asked for **four**, and not three, correct answers. The correct answers include **B, C, E, and F** (the last of which was not indicated in the answer key, page 70).

Item 2

Page 68, Answer Key for Practice Exam question #35 should indicate **B, E, and F** as correct answers (*not* A, B, E).

*Items corrected in **September, 2007** and thus not relevant for copies distributed thereafter.*

Item 1

Page 52, Practice Exam question #1, option C. should correctly refer to Sustainable Sites, Heat Island Effect: Roof as credit number 7.2, rather than 7.1, as it did.